

Stub Axle Replacement

Excessive vertical wobble can be bad bearings. However, in my case it turned out to be badly worn stub axels. Fortunately, I had spotted a set on eBay a couple years earlier, and bought them! Had them installed at Britalia, Fullerton, CA (now closed). I had all the soft parts renewed at the same time.



Figure 1 All parts



Figure 2 Wear pattern